

PROVIDING SOLUTIONS

www.sstlift.com

REPLACING FORKLIFT HOSES

It's Time to Replace Your Hose if You See:

- LEAKING AROUND HOSE FITTINGS can cause performance issues and inefficiencies.
- ABRASIONS can cause equipment failure and put workers at risk of injury.
- EXPOSED WIRE REINFORCEMENT is a sure sign of a need for replacement.
- DAMAGE TO OUTER COVER, SCUFFS OR NICKS can cause leakage and safety concerns.
- TWISTED HOSE, KINKS OR BENDS should be checked by a technician for routing issues.
- CRACKED OR CORRODED FITTING will be seen as red rust created by the hydraulic fluid. This can cause forklift malfunction.

VISUAL INSPECTION:

- Hose showing signs of damage
- Hose showing signs of casing dry rot
- Hose showing signs of excessive stretch (no adjustment remaining)
- Hose due for replacement per the manufacturer guidelines
- Damage showing at the crimped fitting

OPERATIONAL INSPECTION:

- Hose showing signs of fluid seepage
- Hose not tracking on the pulley correctly due to nonadjustable stretch

Replace Before Failure... We Can Help!





Corporate Office · 115 S. 78th Street, Tampa, FL 33619 · (800) 226-2345

4925 Raymond Industrial Dr. Lakeland, FL 33815 (863) 577-5438 Fax (863) 577-5477

13291 Vantage Way, Suite 105 Jacksonville, FL 32218 (904) 493-1150 Fax (904) 493-1160 11000 Palmbay Drive Orlando, FL 32824 (407) 859-3000 Fax (407) 859-9944

1623 N. Magnolia Ave. Ocala, FL 34475 (352) 840-0030 Fax (352) 840-7166 5127 Recker Highway Winter Haven, FL 33880 (863) 967-8551 Fax (863) 965-2681

560 Cynthia Street Jacksonville, FL 32254 (904) 764-7662 Fax (904) 764-1079 1865 Business Parkway Valdosta, GA 31601 (229) 247-8377 Fax (299) 245-7299

7565 Chattsworth Road Columbus, GA 31820 (706) 660-0067 Fax (706) 660-0066 4700 Pio Nono Ave. Macon, GA 31206 (478) 788-0520 Fax (478) 784-1525

1115 Don L. Cutler Sr. Dr Albany, GA 31705 (229) 338-7277 Fax (229) 338-7270

Major Lines

Toyota Material Handling Raymond Autocar Bastian Columbia Combilift JLG Manitou PowerBoss

